

TallyGenicom TechNote GEN_T_012

Parallel Port is not Functional - Models 2265 / 2280, 3116, 7265, LA650 / LA800

Issue / Symptom: The Parallel Port does not Function.

Procedure:

The parallel port is not functional when a TallyCom+ IIF-4 Ethernet card is installed in the printer. The TallyCom+ utilizes a parallel interface connection internal to the printer.

Additional Notes/Comments:

Need help? Call our knowledgeable sales staff at: [708-597-4222](tel:708-597-4222)