

TallyGenicom TechNote GEN_T_023

Ribbon Compatibility - T6200 / 6300

Issue / Symptom: T62XX ribbons can not be used in 6300 Series printers.

Procedures:

The 6300 Series uses a unique ribbon with a different coating on the ribbon sensor disk. You can NOT use a T62XX ribbon in a 6300 Series printer. However, you could use a 6300 Series ribbon in a T62XX printer.

The 6300 Series uses a Hall Effect sensor in the ribbon platform to monitor the ribbon motion disk. This requires a special coating on the disk. If you install a T62XX ribbon in a 6300 Series printer, you will immediately get a ribbon fault when printing starts.

T62XX Ribbons

082727	40M Characters
083683	60M Characters
082725	250M Characters

6300 Series Ribbons

086039	40M Characters
086041	60M Characters
086043	250M Characters

Additional Notes/Comments:

There is no ribbon motion sensor fault override in the 6300 Series. Future code releases of the T62XX series will not have the override either.

Need help? Call our knowledgeable sales staff at: [708-597-4222](tel:708-597-4222)