



Serial Impact Dot Matrix Replacement Guide



A cross reference guide designed to help you quickly find replacements for older printers.

STEP 1: Quickly find your older printer by manufacturer and model number

STEP 2: Cross reference the recommended Tally DASCOM replacement

1 - 800 - 243 - 3338



Tally DASCUM SIDM Printer Series Lineup



T2380 1000 cps



T2365 900 cps



T2280+ 1000 cps



T2265+ 900 cps



T2150 720 cps



T2250 720 cps



T2600 680 cps



T2610 680 cps



T1140/9 400 cps



T1225 375 cps

Tally DASCAM SIDM Speciality Printer Series



LA1000 1000 cps



LA800+ 1000 cps



LA650+ 900 cps



LA550N 720 cps



LA550W 720 cps



LA2600 680 cps



LA2610 680 cps

TABLE OF CONTENTS

CONTENTS

AMT & AT&T REPLACEMENTS.....	4
BROTHER, CITIZEN, & DATAPRODUCTS REPLACEMENTS.....	5
DATASOUTH & DEC REPLACEMENTS.....	6
EPSON & FACIT	7
EPSON (CONT'D) & FUJITSU.....	8
GENICOM	9
IBM/INFOPRINT, LEXMARK & NEC.....	10
OKIDATA, OTC & PANASONIC	11
PRINTEK, SEIKOSHA & TI.....	12
TALLY.....	13
UNISYS.....	14

AMT & AT&T REPLACEMENTS

AMT			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
Accel-212	200	9	T1140
Accel-214	200	24	T2610
Accel-244	225	24	T2610
Accel-292	480	9x2	T2600
Accel -294	480	9x2	T2610
Accel-342	320	24	T2600
Accel-344	320	24	T2610
Accel-535	400	24	T2610
Accel-5350	480	24	T2265+,T2365
Accel-6310	600	24	T2265+,T2365
Accel-6350	600	24	T2265+,T2365
DM3300	333	9	T1140
DM6300	622	18	T2265+,T2365
PP405	600	24	T2265+, T2365
XL300	300	9	T2250
CL400	400	18	T2250

AT&T			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
570	250	9	T2610
571	250	9	T2610
572	250	9	T2610
573	250	9	T2610
577	450	18	T2250
580	200	24	T2610
<u>581</u>	200	24	T2610
583	200	24	T2610

BROTHER, CITIZEN, & DATAPRODUCTS REPLACEMENTS

Brother			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
M-1309	180	9	T1140
M-1324	180	24	T2600
M-1809	300	18	T2600
M-1824L	225	24	T2600
M-1909	300	18	T2610
M-1924L	225	24	T2610
M-2518	300	18	T2610 M-
4018	400	18	T2610
M-4309A	600	18	T2265+,T2365
XL-500	180	9	T1140
XL-1500	180	24	T2600
DataProducts			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
8070	480	18	T2150
8500	520	18	T2265+,T2365
9030	250	9	T1140
9034	250	24	T2600
9040	250	9	T1140
9044	250	24	T2610

Citizen			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
120D	120	9	T1140
GSX-140	160	24	T2600
GSX-140+	180	24	T2600
GSX-145	160	24	T2600
GSX-190	240	9	T1140
GSX-230	194	24	T2600
GSX-240	215	24	T2600
200GX	213	9	T1140
200GX	213	9	T1140
HSP-500	250	9	T1140
HSP-550	250	9	T2610

DATASOUTH & DEC REPLACEMENTS

Datasouth			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
XL300	300	9	T2250
XL400	400	18	T2250
CX3180	180	9	T2610
CX3220	220	9	T2610
CX3400	400	18	T2250
DS180+	180	9	T2610
DS220	220	9	T2610
DS400	400	18	T2250
Dmax 300	250	9	T1140
Pmax A600	622	18	T2265+,T2365
TX5180	180	9	T2610
TX5400	400	18	T2250

DEC			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
LA100	240	9	LA2610
LA120	120	-	LA26N/W
LA180	180	-	LA26N/W
LA195	240	24	LA2610
LA210	240	9	LA2610
LA30N	333	24	LA26N/W
LA30W	300	24	LA2610
LA310	240	9	LA2610
LA324	300	24	LA2610
LA34	30	24	LA26N/W
LA36	360	24	LA26N/W
LA36N-W	360	24	LA26N/W
LA400	400	24	LA2610
LA424	400	2	LA2610
LA450	450	24	LA2610
LA50	100	-	LA2600
LA600	600	24	LA650+
LA65	160	24	LA2600
LA70	200	9	LA2600
LA700	700	9	LA800+
LA75	240	9	LA2600
LA75S	250	24	LA2600
LA75S	250	24	LA2600

EPSON & FACIT

Epson			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
DFX5000	533	9	T2265+,T2365
DFX8000	800	9	T2280+,T2380
FX850	220	9	T1140
FX870	285	9	T1140
FX880	440	9	T2150
FX980	506	9	T2265+,T2365
FX1050	220	9	T2610
FX1170	285	9	T2610
FX1180	440	9	T2250
FX2180	500	9	T2265+,T2365
LQ200	160	24	T2600
LQ510	150	24	T2600
LQ570	210	24	T2600
LQ680	413	24	T2150
LQ850	246	24	T2600
LQ860	246	24	T2600
LQ870	275	24	T2250
LQ1010	150	24	T2610
LQ1050	246	24	T2610
LQ1070	225	24	T2610
LQ1170	275	24	T2610

Epson Printers are continued on the next page

Facit			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
B1200	160	9	T1140
B2100	200	9	T1140
B1250	200	9	T2610
B2400	200	24	T2600
B2450	200	24	T2610
B3100	250	9	T2600
B3100C	250	9	T2610
B3450	250	24	T2610
B3550	400	18	T2250
D2500	240	24	T2600
D2600	240	24	T2610
D M 3000	200	9	T2600
E620	250	9	T2600
E630	250	9	T2610
E670	300	24	T2610
E7650	400	18	T2250
E950	720	24	T2280+,T2380
PP405	600	24	T2265+,T2365
PP406	600	24	T2265+,T2365
PP408	700	24	T2280+,T2380
D2600	240	24	T2610
DM	200	9	T2600

EPSON (CONT'D) & FUJITSU

Epson - Continued			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
LQ2080	400	24	T2250
LQ2180	480	24	T2265+,T2365
LQ2250	333	24	T2250
LX300	220	9	T2600
LX810	200	9	T2600

Fujitsu			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
DL1150	200	24	T2600
DL1250	200	24	T2610
DL3300	240	24	T2600
DL3400	240	24	T2610
DL3800	300	24	T2610
DL4400	220	24	T2610
DL4600	333	24	T2610
DL5600	405	24	T2250
DL5800	420	24	T2250
DX2300	270	9	T1140
DX2400	270	9	T2610

GENICOM

Genicom			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
930	390	9	T2150
935	390	9	T2250
1020	200	18	T2610
1025	200	18	T2250
1040	360	24	T2250
1220	300	24	T2610
3210	240	9	T2610
3320	300	18	T2610
3405	400	18	T2150
3410XLS	400	18	T2250
3510	300	9	T2610
3520	300	9	T2610
3530	400	18	T2250
3540	400	18	T2250
3610-201	300	9	T2610
2420-101	300	9	T2610

Genicom			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
3630-202	400	18	T2250
3640-102	400	18	T2250
3811	1100	18	T2280+,T2380
3810	500	18	T2265+,T2365
3830	500	18	T2265+,T2365
3840	500	18	T2265+,T2365
3850	500	24	T2265+,T2365
3860	600	18	T2265+,T2365
3870	750	18	T2265+,T2365
3880	800	18	T2280+,T2380
3930	500	18	T2265+,T2365
3940	500	18	T2265+,T2365
3972	750	18	T2280+,T2380

IBM/INFOPRINT, LEXMARK & NEC

IBM/Infoprint			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
2380	270	9	T2600
2381	270	9	T2610
2390	180	24	T2600
2391	180	24	T2600
4201	270	9	T2600
4202	270	9	T2610
4207	240	24	T2600
4208	240	24	T2610
4210	200	9	T2610
4212	160	24	T2600
4224- 01	200	9	T2610
4224- 02	400	18	T2610
4224- 03	600	18	T2365
4226- 302	400	9	T2610
4230	400	9	T2610
4232	400	9	T2610
4247- L03	600	24	T2365
4247- X03	800	24	T2380
4247- Z03	100	24	T2380
5204	330	24	T2610

Lexmark			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
2380	270	9	T1140
2381	270	9	T2610
2390	210	24	T2600
2391	210	24	T2610
2480	438	9	T1140
2481	348	9	T2610
2490	409	24	T2600
2491	409	24	T2610
4226	400	9	T2610
4226	400	9	T2610

NEC			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
P1200	160	24	T2600
P2200	140	24	T2600
P5200	220	24	T2600
P5300	220	24	T2610
P6200	250	24	T2600
P6300	250	24	T2610
P3300	180	24	T2610
P9300	333	24	T2610

OKIDATA, OTC & PANASONIC

Okidata			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
180	120	9	T1140
ML172	120	9	T1140
ML180T	155	9	T1140
ML184T	200	9	T1140
ML320	300	9	T1140
ML321	300	9	T2610
ML380	150	24	T2600
ML390+	225	24	T2600
ML391+	225	24	T2610
ML393+	346	24	T2610
ML395	405	24	T2150
ML420	510	9	T2150
ML421	510	9	T2250
ML490	420	24	T2600
ML491	420	24	T2610
ML520	320	9	T2600
ML521		9	T2610
ML590	300	24	T2600
ML591	300	24	T2610
ML240	150	24	T2600
PM2140	350	9	T2610
PM3410	417	9	T2250
PM4410	1066	18	T2280,T2380

OTC			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
560	362	9 x 2	T2250
850XL	800	9 X 3	T2280+,T2380
888XL-2	8009 X3	9 X 3	T2280+,T2380
889XL-2	800	9 X 3	T2280+,T2380
MTP	600	9	T2265+,T2365

Panasonic			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
KX-P1150	160	9	T1140
KX-P1180	160	9	T1140
KX-P1191	200	9	T1140
LX-P1624	160	24	T2610
KX-P1654	250	24	T2610
KX-P1695	275	9	T2610
KX-P2023	160	24	T2600
KX-P2123	160	24	T2600
KX-P2124	213	24	T2600
KX-P2624	200	24	T2610
KX-P3123	160	24	T2600
KX-P3124	213	24	T2600
KX-P3624	200	24	T2610

PRINTEK, SEIKOSHA & TI

Printek			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
930DLX	200	9	T2610
FM8000	800	18	T2280+,T2380
FP2000	200	9	T2610
FP4000	400	18	T2265+,T2365
FP4300	225	9	T2265+,T2365
FP4500	530	9	T2265+,T2365
FP4600	600	9	T2265+,T2365
PM850	530	18	T2265+,T2365
PM852	530	18	T2265, T2365
TI			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
810	150	7	T2610
820	150	9	T2610
830	300	9	T2600
835	300	9	T2610
880	300	9	T2610
885	300	9	T2600
8920	400	18	T2250
8930	400	18	T2250

Seikosha			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
PB-5460	460	8	T2250
BP-5780	520	18	T2265+,T2365
LT-20	120	24	T2600
P900	160	9	T1140
P2400	200	24	T2600
P2400	200	24	T2600
SB-10+	800	18	T2280+,T2380
SK-3000AI	300	9	T2600
SK-3005+	300	9	T2600
SL-90+	200	24	T2600
SL-270	274	24	T2610
SP-2000+	160	9	T2600
SP2000AP	120	9	T2600
SP-2000S	160	9	T2600
SP-2400	200	9	T2600
SP-2415	200	9	T2610
SP-2450	180	9	T2600

TALLY

Tally			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
MT81	130	9	T1140
MT82	160	24	T2600
MT87	200	9	T1140
MT88	200	9	T2610
MT130/9	300	9	T2610
MT130/24	250	24	T2610
MT131/9	300	9	T2610
MT131/24	250	24	T2610
MT150/9	250	9	T2600
MT150/24	300	24	T2600
MT150/9	250	9	T2600
MT150/24	300	24	T2600
MT151/9	250	9	T2600
MT151/24	300	24	T2610
MT220	24	24	T2610
MT230/9	300	9	T2610
MT230/24	300	24	T2610
MT290	200	9	T2610

Tally			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
MT330	300	24	T2610
MT340	400	18	T2250
MT350	450	24	T2250
MT360	600	24	T2265+,T2365
T3860	720	24	T2265+,T2365
MT460D	270	9	T2265+,T2365
MT490	400	18	T2265+,T2365
T2030/9	360	9	T2600
T2030/24	330	24	T2600
T2040	400	24	T2150
T2045	450	24	T2250
T2060	600	2	T2265+,T2365
T2130/9	360	9	T2610
T2130/24	330	24	T2610
T2140	400	24	T2250
T2155	550	24	T2265+,T2365
T2170	700	24	T2280+,T2380

Unisys			
Model	Speed (CPS) @ 10 CPI	Pins	Tally Replacement
AP1324	333	24	T2610
AP1327	270	9	T2600
AP1329	270	9	T2610
AP1337	225	24	T2600
AP1357	300	24	T2600
AP1359	300	24	T2610
AP1371	600	18	T2265+,T2365

***Old Models having 9 pin should be replaced with a 9 needle or, if not, have the 24 needle Printer emulation set to Epson FX.